INSPECTION REPORT

Name of Work	:	IMRPOVEMENTS TO FOOTPATH IN 2ND CROSS ROAD AND OTHER ROADS NEAR SRIRAMA TEMPLE IN MALLASANDRA, WARD NO 13, IN SHETTYHALLI SUB-DIVISION
Work Order	:	EE/DD/WO/338/2014-15 Date 31.3.2015
Agency	:	B UMESH
B.R No & Date	:	B.R.No:266/2015-16, Date: 30-09-2015
Bill Amount	:	Rs.13,95,406/-
Job Code	:	013-15-000004
P.Code	:	P1771
Date of Inspection	:	20-03-2017

The above said work "Improvements to Foot path in 2nd Cross Road and other roads near Sri Rama Temple in Mallasandra, ward no 13 in Shettyhally Sub Div" was shown to me by the Concerned ward Engineer

The above said work is inspected by me along with the Concerned ward Engineer

The work done is Satisfactory

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

Scanned by CamScanner

Name & work:- Sketch Showing the work for Improvements to foot path in 2nd Cross road & other roads near Sirama temple in Mallasandra in ward No. 13 in BBMP



MANJUNATH. K
DOM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

Scanned by CamScanner

Name of Work :- Improvements to Footpath in 2nd cross road and other roads near Sriram temple in Mallasandra, ward no. 13 in Shettyhalli Sub-division.

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಎಸ್.ಎಂ. ರಸ್ತೆ, ಮಲ್ಲೇಶ್ವರಂ, ಬೆಂಗಳೂರು

MANJUNATH. K
DOM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

Scanned by CamScanner

Name of Work:- Improvements to Footpath in 2nd cross road and other roads near Sriram temple in Mallasandra, ward no-13, in Shettyhalli Sub-division.



ದ ೨೦೨೦

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಕೆಂಪಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಎಸ್.ಎಂ. ರಸ್ತೆ, ರಾಜರಾಜೇಶ್ವರಿನಗರ, ಬೆಂಗಳೂರು

MANJUNATH.R
DCM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

Scanned by CamScanner